



1+1 D-S	39 4 VITI TE M 6x30	1+1 D-S	39 4 SCREWS TE M 6x30
	36 4 DADI M 6		36 4 NUTS M 6
	25 1 O-RING Ø 46x2		25 1 O-RING Ø 46x2
	12 1 GIUNTO 1+1		12 1 COUPLING 1+1
	15 1 SPINA Ø 3x10		15 1 PIN Ø 3x10

1+0,5 D	31 1 FLANGIA INTERMEDIA D	1+0,5 D	31 1 MIDDLE PLATE D
	32 1 O-RING Ø 20x1,5		32 1 O-RING Ø 20x1,5
	35 4 VITI TE M 6x35		35 4 SCREWS TE M 6x35
1+0,25 D	36 4 DADI M 6	1+0,25 D	36 4 NUTS M 6
	13 1 GIUNTO 1+0,5		13 1 COUPLING 1+0,5
	25 1 O-RING Ø 46x2		25 1 O-RING Ø 46x2
	15 2 SPINE Ø 3x10		15 2 PINS Ø 3x10
	26 4 VITI TE M 4x20		26 4 SCREWS TE M 4x20

1+0,5 S	41 1 FLANGIA INTERMEDIA S	1+0,5 S	41 1 MIDDLE PLATE S
	32 1 O-RING Ø 20x1,5		32 1 O-RING Ø 20x1,5
	35 4 VITI TE M 6x35		35 4 SCREWS TE M 6x35
1+0,25 S	36 4 DADI M 6	1+0,25 S	36 4 NUTS M 6
	13 1 GIUNTO 1+0,5		13 1 COUPLING 1+0,5
	25 1 O-RING Ø 46x2		25 1 O-RING Ø 46x2
	15 2 SPINE Ø 3x10		15 2 PINS Ø 3x10
	26 4 VITI TE M 4x20		26 4 SCREWS TE M 4x20